

General Environmental Incident Summary

Incident: 3892 **Date/Time Notice:** 9/3/2015 1200 **DEM Incident No:**
Responsible Party: Magellan Pipeline Company, LP
Date Incident: 8/31/2015 **Time Incident:** 1900 **Duration:** 1 days
County: Cass **Twp:** 139 **Rng:** 49 **Sec:** 4 **Qtr:**
Lat: 46.87795 **Long:** -96.88183 **Method:** Interpolation from map
Location Description: 902 Main Avenue East, West Fargo, ND

Submitted By: Scott Benik **Affiliation:** Magellan Pipeline Company, LP
Address: 2728 Patton Road
City: St. Paul **State:** MN **Zip:** 55113

Received By:

Contact Person: Scott Benik
902 Main Avenue East
West Fargo, ND

Distance Nearest Occupied Building: 1000 Feet **Release Contained:** Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Kerosene-based diesel fuel additive

Volume Spilled: 3.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Operator observed stained soil and upon excavating discovered a buried pipe union on a 1-1/2" diameter pipe for a diesel fuel additive. The union was tightened and release stopped. Estimate cause for the union becoming loose is most probably vibration from truck traffic over an extended period.

Risk Evaluation:

None.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None. Full extent of soil was excavated based on extent of odor and staining.

Action Taken or Planned:

Approximately 15 gallons of soil excavated into a drum for management and disposal.

Wastes Disposal Location: Soil will be sampled and managed accordingly.

Agencies Involved:

Updates

Date: 9/8/2015

Status: Reviewed; Followup Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 3 gallons of diesel fuel additive was released under the ground surface due to a leaking pipe. Phone call was made to company contact for verification of cleanup. More followup needed depending on return call from company contact.